



ASSEMBLIES				
Group	Description	Part No	Weight	
			lb	kg
I	Overshot Assy	ON3200	35.35	16.0
II	Cable Swivel	OBNH3121	0.56	0.2

NOTE : Locking sleeve is used in dry hole only. It must be removed when hoisting inner tube.

1	Spiral pin (2) (1/4" X 1 1/2")	ON3222
2	Lifting dog spring	OBNH3116
3	Lifting dog (2)	ONH3119
4	Overshot head	ON3215
5	Machine screw	OBNH3214
6	Lifting dog pivot pin (1/2" X 15/16")	ON3217
7	Spring pin (1) (1/4" X 1 3/4")	ON3218
8	Jar tube weldment	ONH3221
9	Self lock nut	ONH3108
10	Jar staff	ONH3212
11	Locking sleeve	ONH3111
12	Eye bolt	OBNH3102
13	Cable swivel collar	OBNH3103
14	Needle thrust bearing	OBNH3104
15	Nut	OBNH3105
16	Cotter pin (3/32" X 1")	OBNH3106
17	Grease fitting	WB2120
18	Cable swivel body	ONH3207